



SAMWHA ELECTRIC CO., LTD.

3, BONGMYEONG-RO, HEUNG DOK-KU, CHEONGJU-SI, CHUNGBUK, KOREA TEL +82-43-261-0341

Document No. : S/W20200401

Date : April 1st 2020

To : Customers

CC : Samwha Europe GmbH

Sub : China factory situation

We, Samwha Electric Co.,Ltd. always appreciate your strong support.

We would like to inform you current operating situation of China factory

Our China factory re-opened on 21st Feb, but not fully operated yet.

Please see below expected operating ratio in this month.

Product	Operating Ratio	Production Leadtime
Diameter 8mm and less	76%	12 Weeks
Diameter 10mm and more	83%	12 Weeks
SMD	76%	12 Weeks
Snap-in	93%	12 Weeks

We are doing our best to achieve 100% operating ratio to prevent leadtime problem.

For your information, Korea factory is fully operational and no leadtime problem.

We will continuously check the situation and keep you updated.

We wish you healthy even in pandemic situation and thanks for understanding.

SAMWHA ELECTRIC CO., LTD.